


Non-contact Gloss Meter

OPERATION MANUAL



V1.0

Please read this manual carefully before using the instrument

Content

Overview	1
1. External Structure Description	1
2. Measurement Principle and Introduction	3
3. Switch on/off	4
3.1 Startup	4
3.2 Shutdown	4
4. Basic Operation	4
4.1 Menu Operation	4
4.2 Enter the Main Menu	5
4.3 Confirm Prompt Interface	6
4.4 Input Prompt Interface	7
4.5 Editing Operation	8
4.6 Display Item	9
5. Instrument Calibration	9
5.1 Calibrate the Instrument	10
5.2 Modify Calibration Parameters	11
6. Measurement Modes	12
6.1 Switching Measurement Modes	12
6.2 Basic Mode	13
6.2.1 Measurement	13
6.2.2 Basic Mode Menu	14
6.3 Quality Control Mode	15
6.3.1 Interface Introduction	15
6.3.2 Measurement	16
6.3.3 Measure Standard	16
6.4 Statistical Mode	17
6.4.1 Interface Introduction	17
6.4.2 Measurement	18
6.4.3 Measure Standard	18

6.4.4 Set the Number of Measurements	19
6.4.5 Setting Display Options	19
6.5 Continuous Mode	20
6.5.1 Measurement	20
6.5.2 Specified Number of Measurements	22
6.5.3 Specified Measurement Time Interval	22
7. Data Management	22
7.1 Turn on/off the Storage	23
7.2 View Records	23
7.3 Delete Records	23
8. Standard Management	24
8.1 Turn on Difference Display	24
8.2 Browse/Edit/Delete Standards	24
8.3 Measure Standards	25
8.4 Create Standards	26
8.5 Clear Standards	26
9. System Settings	26
9.1 Language Settings	26
9.2 Bluetooth, Address Settings	27
9.3 Beep	27
9.4 Reset the Instrument	27
9.5 View Device Information	28
10. Technical Specifications	28

Non-contact gloss meter

Overview

This non-contact gloss meter has been upgraded from the traditional gloss meter. It can conduct continuous non-contact measurements online and is highly suitable for gloss detection in automated production lines. The product is easy to install and use, and is equipped with corresponding management software. This instrument has two versions: the Bluetooth version (black) and the RS485 enhanced version (blue-black). The interfaces of different versions are different.

1.External Structure Description





Figure 1 External structure

Non-contact gloss meter

RS485 line connection instructions: As shown in the figure below, there are a total of four wires. The following explanations are based on the color of the wires:
(This line is equipped for the PLUS version, and the standard version instrument does not have this port and wiring.)



Button function description

Button name	Icon	Function
Measurement button	⊙	Switch ON/OFF, measurement, quick return to measurement interface, operation confirmation
OK button	✓	Display menu, prompt or operation confirmation
Return button	↶	Return to previous menu or cancel operation
Up button	↑	Move up menu items
Down button	↓	Move down menu items

Remark: Use the above icons to represent the corresponding buttons in the instrument operation prompt

2.Measurement Principle and Introduction

This product complies with international standard ISO2813 and Chinese national standard GB/T9754, and meets the requirements of JJG696 work glossimeter. The non-contact glossimeter has the function of automatic calibration upon startup, and has four measurement modes: basic mode, quality control mode, statistical mode and continuous mode, which can meet different measurement needs. At the same time, the quality management software is provided.

The special design of the non-contact glossimeter provides a 10mm calibration stand, which helps users achieve contact measurement. When the instrument is connected to the 10mm calibration stand (refer to Figure 1), ensure that the instrument is 10mm away from the sample being measured, and contact measurement can be achieved. When the calibration stand is removed (refer to Figure 2), the sample is 10mm away from the bottom of the instrument, and non-contact measurement can be achieved.

The sampling process of the non-contact glossimeter is as follows: in the normal measurement mode, the lighting source is turned on, the sample being measured is illuminated, the detector signal is collected, the lighting source is turned off, and the glossiness of the sample being measured is output. The single measurement time is Approximately 450 milliseconds.




Figure 2 Schematic Diagram of Sampling Principle for Non-contact Gloss Meter

3.Switch on/off

3.1 Startup

The instrument is powered by an external power adapter via the USB interface (or the PLUS version's aviation connector). When using the USB (PLUS version aviation connector), it will automatically start up upon insertion and connection to the power source.

3.2 Shutdown

When powered by USB (PLUS version aviation connector), the device cannot be shut down. To shut it down, simply disconnect the connection.4.Basic.

4.Operation

This chapter introduces some basic operations, which are the basis of the following chapters, and it is best to browse through them.

4.1 Menu Operation




Figure 3 Menu introduction

Non-contact gloss meter

Click the OK button on the measurement interface to enter the menu interface.

In the menu interface, the item displayed in reverse color indicates the currently selected menu item.

Press the up and down buttons to change the currently selected item.

If there is a down arrow (↓) in the lower right corner, it means that there are more menu items that need to be turned up to see; if there is an up arrow (↑) in the upper right corner, it means that there are more menu items that need to be turned up to see.

If there is a triangle symbol (▷) on the right side of the menu item, it means that you can enter the submenu item by clicking the OK button.

Tip 1: Normally press the measurement button on the menu interface to return to the measurement interface.

4.2 Enter the Main Menu

Press the OK button in the measurement interface to enter the menu of the corresponding mode, and select "Main Menu", then press the OK button to enter the main menu.




Figure 4 Main menu

The main menu contains the following items:

- Mode: Select the measurement mode;
- Data: Turn on/off storage function; check and delete records;
- Standard management: Turn on/off the difference value; check, modify, add and delete the standard;
- Calibration: Calibrate the instrument and modify the calibration parameters;
- Setting: System setting.

4.3 Confirm Prompt Interface

The prompt interface is used to prompt to confirm an operation or not like deleting the record as shown in Figure 5.




Figure 5 Delete the record

If you want to confirm the corresponding operation, press the OK button or the Measure button.

Press the return button if you want to cancel the operation.

Tip 2: If confirming “No” in the prompt interface means pressing the return button to perform a “No” operation, and “Yes” means pressing the OK button to perform a “Yes” operation.

4.4 Input Prompt Interface

The input interface is mainly used for prompting input the sample name or number as shown in Figure 6.




Figure 6 Input prompt interface

As shown in Figure 6, between the square brackets (between "[" and "]") is the input area, and the character on "^" is the current input focus.

Press the up or down button to switch the character at the focus position.

Press the OK button to move the input focus to the next position.

Press the measurement button to confirm the entry.

Press the return button to cancel the input operation.

4.5 Editing Operation

The number or character displayed on the right side of some menu items is editable. For example, in the item of the average number of statistical modes, when press the OK button, it will display as shown in Figure 8, which is an edit area enclosed by square brackets. When display the editing area as shown in Figure 8, press the up and down buttons to switch the character at the focus, and press the OK button to move the edit focus to the next character, or press the return button to cancel the changes and press the measurement button to save the changes.



Figure 7 The number of average measurement is editable




Figure 8 Press OK button to edit the number of average times

4.6 Display Item




Figure 9 Display items in edit stats mode will show option box

Some setting values can only be one of several options. For example, in the display item of the statistics mode, press the OK button to select other options.

When you edit an item, it is anti-color display and the current item are enclosed in square brackets.

Press the up or down button to switch the current option.

Press the OK or measurement button to save the changes.

Press the return button to restore the original value.

5.Instrument Calibration

The calibration plate is automatically detected and calibrated when the instrument is turned on.

In order to the accuracy of measurement, it has to re-calibrate it after changing the power supply mode (for battery to USB or from USB to battery power), and it also needs to re-calibrate the instrument after modifying the calibration parameter. If the environment changes too much, it is also better to re-calibrate the instrument.

The related functions are under the Instrument Calibration menu.

Enter the main menu and select “Instrument Calibration” then press the OK button to enter the Instrument Calibration menu.

If you are in the basic measurement mode, you can also find the "calibration" menu item in the basic mode menu.

5.1 Calibrate the Instrument

Before calibration, please confirm that the calibration tile is clean and the calibration plate is in good connection.

During use, enter the “Calibration” menu to calibrate the instrument. Then select “Calibrate” in the “Calibration” menu as shown in Figure 10 and press the OK button.




Figure 10 Press OK button after selecting "Calibrate"




Figure 11 Press measurement button to start calibrate

This will enter the “Calibration” interface, and then press the measurement or OK button to start calibrate the instrument as shown in Figure 11.

When the instrument is calibrating, it will display “Calibrating” and flashes green light.

After the calibration is completed, if the calibration is successful, it is as shown in Figure 12. At this time, press the measurement button to return to the measurement interface or press the return button to return to the “Calibration” menu . If the calibration is failure, it is as shown in Figure 13. Press the measurement button or the OK button to retry, or press the return button to cancel it.




Figure 12 Calibration pass




Figure 13 Calibration fail

5.2 Modify Calibration Parameters

Please modify the calibration plate parameters in the instrument simultaneously if replace or re-calibrate the calibration tile.




Figure 14 Modify the calibration board parameters

Please enter the “calibration” menu to modify the calibration tile parameters, then select the “modify parameters” menu item and press the OK button to enter the “modify parameters” interface.

Select the angle to be modified and press the OK button to start editing the corresponding value. Press the measurement button to save the changes after finishing the editing.

Note: The random change of the calibration tile parameters will lead to the inaccuracy of measurement. Please consult the factory to re-calibrate the calibration tile or replace the calibration plate.

6.Measurement Modes

6. 1 Switching Measurement Modes

The instrument is in the basic mode when it is turned on for the first time. Please enter the “main menu” and select the “measurement mode” menu item, then press the OK button to the “Mode” interface to change the measurement mode as shown in Figure 15. Select the appropriate measurement mode and press the OK button.




Figure 15 Measurement mode menu

6.2 Basic Mode

6.2.1 Measurement

Press the measurement button under the basic mode interface to measure. During the measurement, the green indicator lights up, while the green indicator goes out after the measurement is completed and display the measurement results as shown in Figure 16.




Figure 16 Basic mode measurement results




Figure17 Enter the sample name

Non-contact gloss meter

If the storage function is turned on, it prompts to enter the sample name after each measurement is completed as shown in Figure 17. The system will provide a default name and press the measurement button to confirm the name and save it or press the return button to cancel it.

Press the return button to delete the measurement result as shown in Figure 18.




Figure 18 Press the return button to delete the measurement result

6.2.2 Basic Mode Menu

Press the OK button at the measurement interface to enter the basic mode menu.



Figure 19 Select "Main Menu" and press the OK button to enter the main menu

The basic mode menu contains the following menu items:

- The main menu: Enter the main menu;
- Delete: Delete the current measurement result;
- Storage: Enable or disable the storage function. If the storage function is turned on, "ON" will be displayed on the right, otherwise "OFF" will be displayed.
- Calibration: Functions related to instrument calibration, see 5 Instrument Calibration;
- Setting: Enter the system setting menu, see 10 System Setting.

6.3 Quality Control Mode

6.3.1 Interface Introduction

STD 01	SAMP 001		
	value	diff	pass
60°	14.7	0.0	OK

Figure 20 Figure 19 Select "Main Menu" and press the OK button to enter the main menu

The standard interface of the quality control mode is shown in the figure above, the upper left corner is the name of the current standard sample, and the upper right corner is the name of the current sample.

As shown in Figure 20, the "value" column shows the measured value; the "diff" column shows the difference between the sample value and the standard value; the "pass" column shows judgement results, and "OK" means within the tolerance of the standard, "NG" indicates out of tolerance.

If the difference display is not turned on, the measurement interface of the quality control mode is the same as the basic mode.

6.3.2 Measurement

Press the measurement button in the measurement interface to measure. The green light will light up during measurement, and will go out after the measurement is completed and the measurement result will be displayed.

6.3.3 Measure Standard

Press the OK button to enter the quality control mode menu, then select the measurement standard. After the measurement is ready, press the OK button to measure.

After the measurement is completed, the measurement result is displayed and prompted for confirmation as shown in Figure 21.




Figure 21 Confirm the measurement result of standard




Figure 22 Enter the sample name

Press the OK button to confirm or press the return button to discard the result.

If the storage function is turned on, it prompts to enter the standard name after the confirmation is finished as shown in Figure 22.

After confirming the name of the standard, press the measurement button to save the standard or press the return button to cancel the storage. At this time the standard will be save as a temporary standard.

After the standard is measured, it is automatically set as the current standard; if the differential display is not turned on, it will be automatically turned on.

6.4 Statistical Mode

6.4.1 Interface Introduction

As shown in Figure 23, in the top left corner of the statistics mode, it displays the current standard name. The first row in the upper right corner shows the current sample name, and the second row shows the number of measurements, which is displayed in the form of "m/n". "m" indicates the number of measured times and "n" indicates the total numbers of requirement measurement.

In the figure 23, "avg", "range", "stdev" each shows the average value, the variation range of m measurements, and the standard deviation. They can be changed in the Display Options in the Statistics Mode menu.

STD 03	SAMP 001		
			9/9
	avg	range	stdev
60°	14.6	0.4	0.0

Figure 23 Statistics Mode Measurement Interface

6.4.2 Measurement

After entering the statistical mode measurement interface, press the measurement button to measure. The measurement result will be updated at each measurement, and measurement will be automatically performed after the specified number of measurements. If the storage is turned on, it will prompt to enter the sample name when measurement is finished.

Please press the down button to finish the current measurement if the setting numbers of measurements are not enough.

Please press the up button (this operation can only be performed when the measurement is not completed) to delete the previous measurement data.

Please press the return button to delete the measurement result.

6.4.3 Measure Standard

Press the OK button to enter the statistical mode menu, then select the “Measure Standard” menu item, and press the OK button to enter the standard measurement interface.

The "m/n" in the top left corner of the measurement interface shows the current number of measurements and the total number of required measurements.

The "avg" column in the measurement interface shows the average of m measurements; the "min" column shows the minimum value in m measurements, and "max" shows the maximum value in m measurements.

Measure	Standard		
	avg	min	max
60°	14.7	14.7	14.7

Figure 24 Statistics mode measurement standard interface

After entering the standard measurement interface, press the measurement button to measure. After measuring for a specified number of times, if the storage is turned on, it will be prompt to input the standard name, otherwise it is set as a temporary standard.

During the measurement, press the return button to cancel the measurement or press the OK button to complete the measurement.

6.4.4 Set the Number of Measurements

Enter the statistics mode menu and select the "Average" menu item, then press the OK button to modify the number of measurements.

The number of measurements in the statistical mode can be set from 2 to 99 .

6.4.5 Setting Display Options

After entering the statistics mode menu, select the "Display Options" menu item, and then press the OK button to enter the display options setting page.

The statistical mode measurement interface can display up to three columns, corresponding to the first, second and third items respectively.

The available display items are:

- "avg": Average;
- "min" : The minimum value of the measured value;
- "max" : The maximum value of the measured value;
- "range" : The value that the maximum value minus the minimum value;
- "stdev" : Standard deviation;
- "diff" : Difference that minus the standard deviation;
- "pass": The result of comparison with the standard sample, "OK" or "NG";
- Blank: no display.

The standard deviation calculation formula is:

$$\text{stdev} = \sqrt{\frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n - 1}}$$

6.5 Continuous Mode

6.5.1 Measurement




Figure 25 Continuous measurement interface (Ready)

Press the measurement button in the continuous measurement interface to start measurement.

If the storage is enabled, it will prompt to enter a name before the measurement. This name will be used as the first measurement name as shown in Figure 26, and subsequent measurements will be automatically incremented based on the name.




Figure 26 Enter the name of the first measurement

As shown in Figure 27, During the measurement process, the current measurement result and the number of the ongoing measurement will be displayed.




Figure 27 Continuous measurement interface (Measuring)

Press the measurement button or the return button during measurement to pause the measurement. When the measurement is paused, the average value ("avg" column), minimum value ("min" column), and maximum value ("max" column) of all measured samples are displayed as shown in Figure 28. Press the measurement button again to continue measurement.




Figure 28 Continuous measurement interface (Pause)

Press the OK button while paused to abort the measurement and press the OK button again to display the continuous mode menu.

When the measurement is performed a specified number of times, the measurement is stopped and the average, minimum, and maximum values of all measured samples are displayed.




Figure 29 Continuous measurement interface (Complete)

6.5.2 Specified Number of Measurements

In the measurement interface, press the OK button to enter the continuous mode menu (If measurement is in progress, it needs to stop the measurement first), and select the "measurement times" menu item then press the OK button to modify. The number of measurements can be specified from 1 to 15000.

6.5.3 Specified Measurement Time Interval

In the measurement interface, press the OK button to enter the continuous mode menu (If measurement is in progress, it needs to stop the measurement first), and select the "Measurement interval" menu item then press the OK button to modify. The measurement time interval can be specified from 1 to 120 seconds. The measurement time interval refers to the interval of two measurements.

7.Data Management

Enter the main menu to select the "Storage" menu item and press the OK button to enter the data management interface.




Figure 30 Storage menu

7.1 Turn on/off the Storage

Select the "Storage" menu item and press the OK button. After modifying the switch options, press the measurement button to save the changes.

7.2 View Records

Record types are divided into quality control records, statistical records, and basic records. The quality control records store the quality control measurement results; the statistical records store the statistical measurement results; the basic records store the basic model and continuous model measurement results.

To view the corresponding record, select the appropriate record and press the OK button to start browsing.

Press the up or down button during browsing to switch the records.

Press the return button to return to the storage menu.

Press the measurement button to return to the measurement interface.

7.3 Delete Records

Select the "Delete" item of the storage and press the OK button to enter the "Delete" menu. Then select the record type to delete, press the OK button after selecting, and it will prompt to confirm the operation by pressing the OK button or the measurement button or cancel it by pressing the return button.

Note: The delete operation will empty all corresponding records at once, so please operate with caution.

8. Standard Management

In the main menu, select "Standard Management" and press the OK button to enter the standard management menu.




Figure 31 Standard management menu

8.1 Turn on Difference Display

In the standard management menu, select "Difference Display" and press the OK button to modify the difference display switch. After the modification, press the measurement button or OK button to save the changes.

8.2 Browse/Edit/Delete Standards

In the standard management menu, select "Browse Standards" and press the OK button to enter the browse standards interface as shown in Figure 32.

Standard	value	lower	upper	
STD 01	60°	14.7	0.0	2000

Figure 32 View standards interface

In the figure 32, the upper right corner shows the standard name. If it is the current standard, "*" will be displayed in front of the name.

"value" is the target value of the standard, "lower" is the lower limit of the qualified sample, and "upper" is the upper limit. In the quality control or statistical mode, within the range of upper and lower limits are "OK", exceeding it is "NG".

Press the up or down button while browsing the standard to switch the standard.



Figure 33 View standards menu

Press the OK button to open the browse standards menu, as shown in Figure 33.

The View standards menu includes:

- Set as the current standard: set the browse standard as the current standard;
- Modify the standard: modify the name and value of the viewing standard;
- Delete: delete the viewing standard.

8.3 Measure Standards


In the standard management menu, select "Measure" and press the OK button to perform the measurement.

Use average measurements in statistical mode, otherwise use basic measurements.

The average measurements procedure is similar to the standard measurement under the statistical mode standard menu. The basic measurement is similar to the standard measurement in the quality control mode.

8.4 Create Standards

Select "Create" in the standard management menu and press the OK button to create a new standard, as shown in Figure 34. Then, in the "Create Standards" interface, modify the name of the Standard and set the target value and upper and lower limits for each angle.



The screenshot shows a 'Create' interface with the following fields and values:

Field	Value
Name	STD 06
Target	0000.0
Lower	0000.0
Upper	2000.0

Figure 34 Create standards interface

8.5 Clear Standards

Clear Standards will delete all stored standards.

In the standard management menu, select "Clear" and then press the OK button.

The system will prompt to confirm. Press the measurement button or OK button to execute the emptying operation or cancel it by pressing the return button.

9. System Settings

In the main menu, select the "Setting" menu item and press the OK button to enter the System Settings menu.

9.1 Language Settings

After selecting "Language Settings" in the system settings menu, press the OK button to enter the language menu. Select the required language and press the OK button to set it as the system language.

9.2 Bluetooth, Address Settings

Bluetooth (Standard Version)

To turn on Bluetooth, you can connect to a Bluetooth-enabled device for communication. To turn off Bluetooth, you cannot connect using Bluetooth.

Address Setting (PLUS Version)

This function allows you to set the instrument to communicate with the device end. It works when connecting to an aviation plug. Each instrument can have a different address, enabling multiple instrument connections to the device for controlled measurement. This allows for multiple simultaneous measurements and enables automated measurements for more instruments. Note: Using the same address may cause uncontrollable errors. Please ensure that the instrument addresses for communication are different.

Note: Using the same address may cause uncontrollable errors. Please ensure that the communication addresses of the instruments are different.

9.3 Beep

In the system settings menu, select the "Beep" menu item and press the OK button, then modify the switch options. After the modification is completed, press the OK button or the measurement button to save the changes.

9.4 Reset the Instrument

Reset the instrument when the system is abnormal.

Resetting the instrument will erase all user data and settings except calibration tile parameters, so please use it with caution.

Press the OK button after selecting "Reset Instrument" in the system menu. At this time, the system will prompt to execute the operation or not. If confirm to execute the operation, please press the OK button or measurement button, or cancel the operation by pressing the return button.

Non-contact gloss meter

9.5 View Device Information

In the system menu, select "Device Information" and press the OK button to view the device information.

The device information includes the instrument model ("Model"), serial number ("SN"), software version number ("S.V."), and hardware version number ("H.V.").

10. Technical Specifications

Non-contact Gloss Meter (Standard Version)

Product Model	Non-contact Gloss Meter (Standard Version)
Measuring Angle	60°, Conform to Standards: ISO 2813, ASTM D 523, GB/T 9754
Measuring Spot(mm)	60°:9X15
Measurement Range	60°:0~1000GU
Division Value	0.1GU
Non-contact Distance	Non-contact distance 10.0mm±0.1, the parallelism between the measured surface of the sample and the measuring aperture surface is 0.2 degrees
Features	It can be used for gloss measurement and quality inspection in paint ink, coating, paper printing, plastic electronics, furniture, ceramics, electroplating, hardware, marble and other industries. The non-contact test between the test probe and the tested sample realizes the non-contact test of samples such as liquids, pastes, powders, and fragile objects. The measurement time can be as fast as 0.2 seconds, and it can communicate with other systems through Bluetooth or USB, and demonstrate routines of various communication interfaces. Software functions can be customized (according to the evaluation of the situation, additional customization fees will be generated).
Measuring Modes	Basic Mode, Statistical Mode, Continuous Mode, Quality Mode
Measuring Time	0.2s/1s
Repeatability	0~100GU: ±0.5GU ; 100~1000GU: ±0.5%GU Test at intervals of 5 seconds under 10mm verification tooling (ensure test distance 10 and parallelism)
Accuracy	Meet the requirements of JJG 696 working gloss meter
Language	Simplified Chinese, English, Traditional Chinese
Storage	35000pcs(15,000 records in basic mode and continuous mode, 10,000 records in quality control mode, and 10,000 records in statistical mode)
Display	2.3 inch black and white display

Non-contact gloss meter

Dimension	140X83X38mm(Not including calibration bracket and calibration plate)
Weight	About 500g
Power Supply	Use the USB interface power adapter
Data Port	USB, Bluetooth
PC Software	Quality management software, quality inspection report printing, more function expansion
Operation Temperature Range	0~40°C(32~104°F)
Storage Temperature Range	-20~50°C(-4~122°F)
Humidity	Less than 85%RH, no condensation
Standard Accessories	Power adapter, quality management software (official website download or after-sales), calibration plate, calibration bracket

Non-contact gloss meter

Non-contact Gloss Meter (PLUS Enhanced Version)

Product Model	Non-contact Gloss Meter (PLUS Enhanced Version)
Measuring Angle	60°, Conform to Standards: ISO 2813, ASTM D 523, GB/T 9754
Measuring Spot(mm)	60°:9X15
Measurement Range	60°:0~1000GU
Division Value	0.1GU
Non-contact Distance	Non-contact distance 10.0mm±0.1, the parallelism between the measured surface of the sample and the measuring aperture surface is 0.2 degrees
Features	It can be used for gloss reduction and quality inspection in industries such as paint and ink, coatings, paper printing, plastic electronics, furniture, ceramics, electroplating, hardware, marble, etc. The test probe and the sample being tested conduct non-contact tests, enabling non-contact tests on liquids, pastes, powders, fragile objects, etc. The measurement time can be as fast as 0.2 seconds. It can communicate with other systems via USB or RS485. There are various communication interface demonstration programs. Software functionality customization is available (depending on the assessment, additional customization fees may apply).
Measuring Modes	Basic Mode, Statistical Mode, Continuous Mode, Quality Mode
Measuring Time	0.2s/1s
Repeatability	0~100GU: ±0.5GU ; 100~1000GU: ±0.5%GU Test at intervals of 5 seconds under 10mm verification tooling (ensure test distance 10 and parallelism)
Accuracy	Meet the requirements of JJG 696 working gloss meter
Language	Simplified Chinese, English, Traditional Chinese
Storage	35000pcs(15,000 records in basic mode and continuous mode, 10,000 records in quality control mode, and 10,000 records in statistical mode)
Display	2.3 inch black and white display

Non-contact gloss meter

Dimension	140X83X38mm
Weight	About 500g
Power Supply	Use a USB interface power adapter or an aviation plug for connection
Data Port	USB, RS485
PC Software	Quality management software, quality inspection report printing, more function expansion
Operation Temperature Range	0~40°C(32~104°F)
Storage Temperature Range	-20~50°C(-4~122°F)
Humidity	Less than 85%RH, no condensation
Standard Accessories	Power adapter, quality management software (official website download or after-sales), calibration plate, calibration bracket



2.004.01.0206